




Junction Mount	Pole Mount
PFA121	PFB121+ PFA152-E
 A line drawing showing a camera unit mounted on a flat surface. The camera is connected to a rectangular junction box with four mounting screws. The junction box is mounted to the surface with four screws.	 A line drawing showing a camera unit mounted on a vertical pole. The camera is connected to a rectangular junction box. The junction box is mounted to the pole using two metal straps with buckles.
Corner Mount	
PFB121 + PFA151	
 A line drawing showing a camera unit mounted on the corner of a structure. The camera is connected to a rectangular junction box. The junction box is mounted to the corner using a metal bracket with four screws.	